

12 things to consider when selecting an industrial accelerometer

Selecting an industrial accelerometer – what to consider

#1 – Acceleration range

- Most industrial applications utilize a sensor with an 80 g or 50 g acceleration range
 - 80 g sensors provide a broader dynamic range of measurement
 - 50 g sensors may clip the signal, resulting in sensor overload, if the amplitude of vibration extends beyond the acceleration limit




#2 – Reliable signal over the life of the sensor

- Many physical characteristics contribute to accurate sensor data over the long-term
 - Piezoelectric stabilization of the PZT crystal minimizes signal drift over time
 - True hermetic seal (verified by helium leak testing) protects internal components from outside contaminants)
- Can the manufacturer provide Mean Time Between Failure data

Selecting an industrial accelerometer – what to consider

#3 – Sensitivity tolerance

- Typical sensitivity tolerance range from 5% to 20%
 - A tight tolerance of 5% is the best
 - A wider 10-20% tolerance can be used when the exact sensitivity value can be programmed into the data acquisition equipment
 - Tolerances are most important if your data collector or online system does not easily allow changing sensitivities for individual accelerometers



#4 – What you get is what you expect

- Make sure sensor meets specifications on datasheet
 - Some datasheets quote guaranteed specifications, while many give “typical” specifications that your sensor may not meet
 - Have confidence that the performance of the product meets the advertised specifications
 - Especially important for frequency response and noise specifications
-

Selecting an industrial accelerometer – what to consider

#5 – Acceleration versus velocity

- Acceleration and velocity sensors monitor for different faults
 - Velocity sensors are used for the majority of applications because velocity is the best overall indication of machinery health for both low speed and high speed components
 - Acceleration is useful for monitoring gear mesh frequencies and early warning signs for bearing failure
 - Both sensor outputs are available with a variety of options: top or side exit, a range of sensitivities and tolerances, integral cabling, and hazardous area certifications

#6 – Hazardous area certifications

- Make sure sensor meets specifications on datasheet
 - Vibration sensors are available with hazardous area certifications commonly found in industrial settings including Intrinsically Safe Class I Division 1 / Zone 0, Class I Division 2 / Zone 2, and Explosion Proof ratings



Selecting an industrial accelerometer – what to consider

#7 – Resonance frequency

- Resonance frequency can mask developing faults if it is not far enough from the signal of interest: 30 kHz is usually adequate

#8 – Temperature range

- Temperature where the accelerometer will be installed determines type of accelerometer you choose
 - Standard industrial accelerometers with built-in electronics are limited to 248° F (120° C)
 - High grade components enable some sensors to reach 302° F (150° C)
 - ‘Charge mode’ accelerometers, which do not contain internal electronic circuitry, typically operate up to 500° F (260° C)
 - Special high temperature sensing elements enable operation at temperatures as high as 1400° F (760° C), however these units present other trade offs in industrial environments, so it’s important to balance temperature requirements with factors including price/ruggedness
 -

Selecting an industrial accelerometer – what to consider

#9 – Integral cabling



- All integral cables are not created equal
 - Ceramic to metal headers separate internal sensor parts from cable to keep all moisture and contamination out of sensor
 - Testing at only specification pressure level can mask a fracture; for deep underwater applications, sensor testing should include cycling to expand fractures
 - Deep underwater applications should employ a cable with insulation that reduces damage to cable if water does enter it
 - Special consideration should be given to cable/boot interface to make certain moisture does not penetrate sensor through boot assembly

Selecting an industrial accelerometer – what to consider

#10 – Isolation and shielding



- Sensor and cable design should protect signal from environmental factors that can corrupt data
 - Shielded cable is required with the shield terminated at the enclosure (not the sensor) to avoid ground loops and static charge build up
 - Sensors should be designed to withstand ESD (electro-static discharge) up to 20,000 Volts, however this specification is not typically listed on data sheets and should be requested of the manufacturer
 - Mounting pads can be purchased to provide isolation protection (up to 1,500 Volts) in environments when there may be high voltage potential differences, high static charge build up, or uncertain grounding conditions

Selecting an industrial accelerometer – what to consider

#11 – Measurement range


- 100 mV/g sensors are most commonly used to monitor industrial rotating equipment, but there are exceptions
 - 10 mV/g sensors for high-g applications such as high speed turbines or monitoring second and third harmonics of gear mesh frequencies
 - 500 mV/g sensors for low frequency applications such as monitoring wind turbine blades or slow moving machinery in cooling towers

#12 – Technical support

- Given the number of important considerations in accelerometer selection, technical support from the manufacturer and a knowledgeable sales team are critical to selecting the correct accelerometer for your application

Wilcoxon Sensing Technologies

For more information, please contact us:

 +1 (301) 330 8811

 info@wilcoxon.com

 www.wilcoxon.com

The information contained in this document is the property of Wilcoxon Sensing Technologies and is proprietary and/or copyright material. This information and this document may not be used or disclosed without the express authorization of Wilcoxon Sensing Technologies. Any unauthorized use or disclosure may be unlawful.

The information contained in this document may be subject to the provisions of the Export Administration Act of 1979 (50 USC 2401-2420), the Export Administration Regulations promulgated thereunder (15 CFR 730-774), and the International Traffic in Arms Regulations (22 CFR 120-130). The recipient acknowledges that these statutes and regulations impose restrictions on import, export, re-export and transfer to third countries of certain categories of data, technical services and information, and that licenses from the US Department of State and/or the US Department of Commerce may be required before such data, technical services and information can be disclosed. By accepting this document, the recipient agrees to comply with all applicable governmental regulations as they relate to the import, export and re-export of information.'